



GE
Sensing & Inspection Technologies

1100 Technology Park Dr.
Billerica, Mass. 01821
USA

T 1 877 243 5086
E sensing@ge.com
www.gesensinginspection.com

IMPORTANT SAFETY RECALL

Recipient name
Recipient title
Recipient address
Recipient address

February 18, 2010

Dear **NAME**:

In cooperation with the U.S. Consumer Product Safety Commission (CPSC), GE Sensing & Inspection Technologies is notifying distributors and customers that we will be voluntarily replacing all Telaire T5010, T5010-C, T5011, T5011-C, T8010, T0810-C, T8011, and T8011-C CO₂ sensors to eliminate a possible fire hazard.

What happened: GE has learned of three overheating and smoking incidents involving these models manufactured between 2000 and 2005.

What to do: GE is conducting a formal replacement program. GE will offer free replacement Telaire CO₂ sensors and requests the return of all existing sensors to GE. If you have Telaire CO₂ sensors included in the replacement program, you should contact GE immediately U.S. Toll-free at +1 877-243-5086 (Toll +1 814-834-5699) or visit www.gesensing.com to schedule a free replacement. Additionally, customers should monitor the sensors every two weeks. If a sensor installed in the field is not operating properly, you are advised to disable the sensor.

You can find instructions for identifying whether you possess a Telaire CO₂ sensor included in the replacement program, how to obtain a replacement sensor, and whether you may continue to use sensors while awaiting replacement sensors on the "Recall Information" page at www.gesensing.com.

We apologize for any inconvenience. Thank you for your immediate attention to this matter and for facilitating the replacement of these sensors. The safety of our customers is our highest priority.

Sincerely,

Kermit Hoffman
GM Advanced Sensors
GE Sensing and Inspection Technologies